## RoeTest - Computer Tube Tester / Tube Measuring System (c) - Helmut Weigl www.roehrentest.de

If there arise problems after a software update – something ceases to work correctly - the reason could be that the settings have been overwritten.

